IN THE UNITED STATES PATENT & TRADEMARK OFFICE

IN RE APPLICATION OF: U.S.	Patent No. 7,881,745

USPTO CONFIRMATION CODE: 4061

ATTORNEY DOCKET NUMBER: 200701940-2

APPLICATION NO.: 10/797,176

FILED: Mar. 10, 2004

EXAMINER: PIERRE LOUIS DESIR

GROUP ART UNIT: 2617

FOR: ELECTRONIC DEVICE NETWORK EMPLOYING PROVISIONING TECHNIQUES TO UPDATE FIRMWARE AND/OR SOFTWARE IN ELECTRONIC DEVICES

37 CFR 1,322 & 37 CFR 1,323 REQUEST FOR CERTIFICATE OF CORRECTION

HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS

Sir

The following is a request for a certificate of correction in Serial Number 10/797.176, now Patent Number 7.881.745.

A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent.

ee is required, please charge the amount to Deposit Account No. 082025.
All errors were the fault of the applicant and, accordingly, please charge \$100.00 of our Deposit Account No. 082025. In the event that a further fee is required, please
tharge the amount to the same Deposit Account.

All errors were the fault of the USPTO, no fee required. In the event that a further

The errors were the fault of both the applicant and USPTO and, accordingly, please charge \$100.00 to our Deposit Account No. 082025. In the event that a further fee is required, please charge the amount to the same Deposit Account.

The exact locations where the errors appear in the patent and patent application are as follows:

In column 16, line 49, in Claim 13, delete "at least server" and insert -- at least one server --, therefor.

(Amendments to claims filed on Oct. 19, 2010, page 9, in claim 14, line 5)

In column 17, line 59, in Claim 19, delete "claim 18" and insert - - claim 18, - -, therefor,

(Amendments to claims filed on Oct. 19, 2010, page 12, in claim 22, line 1)

The requested corrections are attached on Form PTO 1050.

Respectfully Submitted

4/13/11 /Ted McCullough/

Name: Theodore C. McCullough Registration No.:56,231

Attorney/Agent of Record

HEWLETT-PACKARD COMPANY Intellectual Property Administration 3404 E. Harmony Road Mail Stop 35 Fort Collins, CO 80528

DATE

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO. : 7,881,745

APPLICATION NO.: 10/797,176

ISSUE DATE : Feb. 1, 2011

INVENTOR(S) : Bindu Rama Rao et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 16, line 49, in Claim 13, delete "at least server" and insert - - at least one server - -, therefor.

In column 17, line 59, in Claim 19, delete "claim 18" and insert - - claim 18, - -, therefor.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Hewlett-Packard Company Imelicetual Property Administration 3404 E. Harmony Road Mail Stop 35

Fort Collins, CO 80528

This collection of information is required by 3 C.PR. J. 322, and 3.323, and 1.333. The information is required to obtain or retein a border for the guide which is to fit (ind by the ISPITO of process an application). Confidentially we governed by 5 C.S.P. L. 220 and 5 V/FE 1.1.4. This collection is resistanted to be use 1 to live its Complete, michaling gainering, preparing, and submitting the completed explication from to the USP/UT. Time will very depending upon the individual case. Any comments on the automat of time you require to complete this few and of vingoristics for retein, in this bunder, should be sent to the Clin Information Collection. US. Paters and Trackmark (Office, Clin Endeaved Collection, C